09/848046

**PATENT** 

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number:

6,887,652 B2

Docket No. YAMAP0594USA

Issued:

May 3, 2005

Name of Patentee:

Hino, et al.

Title of Invention:

HIGH DENSITY OPTICAL DISK, APPARATUS FOR REPRODUCING OPTICAL

DISK AND METHOD FOR PRODUCING OPTICAL DISK MASTER

**Assistant Commissioner for Patents** P.O. Box 1450

Alexandria, VA 22313-1450

**ATTENTION: Decision and Certificate of Correction** 

**Branch of the Patent Issue Division** 

Certificate

JUL 2 5 2005 of Correction

## REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R. § 1.322(a))

- 1. Attached, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.
- 2. The exact page and line number where the errors are shown correctly in the application file are:

Original Claim 9, "wherein step (d)" should read --wherein the step (d) --; and "second beam having" should read -- second beam trace having --.

3. Please send the Certificate to:

Name:

Mark D. Saralino

Address:

Renner, Otto, Boisselle & Sklar, LLP

1621 Euclid Avenue, 19th Floor

Cleveland, OH 44115

Mark D. Saralino Attorney of Record

Reg. No. 34,243

Renner, Otto, Boisselle & Sklar, LLP 1621 Euclid Avenue, 19th Floor

Cleveland, Ohio 44115

(216) 621-1113

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,887,652 B2

DATED

May 3, 2005

INVENTOR(S)

Yasumori Hino; Norio Miyatake; Tadashi Nakamura

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 16, line 10, "wherein step (d)" should read -- wherein the step (d) --; and line 11, "second beam having" should read -- second beam trace having - -.

MAILING ADDRESS OF SENDER:

Renner, Otto, Boisselle & Sklar, LLP 1621 Euclid Avenue -- Nineteenth Floor Cleveland, Ohio 44115-2191

No. of additional copies at \$0.30 per page.

Patent No. <u>6,887,652 B2</u>

PTO-1050 PTO/SB/44

Juli 2 6 2005